NOTICE OF SPECIFIED PENALTY				
Date of Issue: May 30, 2017		Payment Due Date: June 30, 2017		
MSA File Number	2017-195	Specified Penalty Amount	\$250	
Registered Entity Name	Suncor Energy Inc.			
Asset ID (if applicable)	SCR6	Self-Report	⊠ YES □ NO	
ISO Rule	306.5	Date of Contravention	April 19, 2017 to May 24, 2017	
Date of Referral/Self Report	May 3, 2017	This is the first contravention by this asset for this rule within a rolling 12 month period.		

EVENT DETAILS

On April 4, 2017 Suncor Energy Inc. submitted planned outage information regarding two units associated with its SCR6 generation asset, GT8 and GT10. GT8 and GT10 were each scheduled to be on outage for portions of April and May 2017. Information available to the MSA indicates that Suncor Energy Inc. had planned these outages in January 2017, and therefore had not submitted the outage information to the ISO as soon as reasonably practical.

Subsection 3 of section 306.5 of the ISO rules states, in part:

- (2) A pool participant must, by the first (1st) day of every month after the date of energization, submit the information set out in subsection 3(1) to the ISO related to planned outages that, as of the time of the submission, are planned to occur at any time within the next twenty-four (24) months.
- (3) A pool participant must, with respect to:
 - (a) any revisions to the information submitted to the ISO under subsection 3(1); or
 - (a) [sic] a planned outage that is not included in the submission set out in subsection 3(2); submit such information or planned outage as soon as reasonably practical.

FINDINGS

Based upon the information obtained by the MSA, the MSA is satisfied that the event was a contravention of ISO rule 306.5.

MATERIAL FACTS

The material facts relied upon by the MSA include the following:

- 1. AESO available capability restatement data for SCR6 for April 19, 2017.
- 2. Self-report submitted by Suncor Energy Inc. to the MSA dated May 3, 2017.
- 3. Additional information provided by Suncor Energy Inc. on May 26, 2017.

DELIVERY OF PAYMENT

Payment by cheque or certified funds is to be made out to the "General Revenue Fund c/o Minister of Finance", and delivered to the Alberta Utilities Commission (AUC) at: 4th Floor, 425 - 1st Street S.W., Calgary, Alberta, T2P 3L8. Questions in respect of delivery of payment should be addressed to the Director of Finance, AUC. The payment should reference this notice and related MSA File #. Delivery of payment should also be confirmed by email to compliance@albertamsa.ca, with copy to the following AUC personnel: Jeremy Smith (Financial Accountant) jeremy.smith@auc.ab.ca, and Greg Andrews (Investigator) greg.andrews@auc.ab.ca.

NOTICE

The Market Surveillance Administrator (MSA) is granted the power and authority under s. 52 of the *Alberta Utilities Commission Act* to issue a Notice of Specified Penalty where the MSA is satisfied that a person has contravened an ISO rule. Specified penalties are set out in AUC Rule 019.

In accordance with the relevant enactments and rules, a dispute regarding the issuance of a Notice of Specified Penalty or failure to pay the specified penalty in accordance with this notice will result in a hearing or other proceeding before the AUC.

In accordance with s. 5(1) of AUC Rule 019 this Notice of Specified Penalty will be made public no earlier than receipt of confirmation of payment from the Commission and no later than 45 days after issuance. The MSA will, if applicable, also post on its website the link to any decision of the AUC respecting the specified penalty.

If your organization disputes the issuance of this Notice of Specified Penalty, or if you have any other questions or comments regarding this matter, please contact the MSA compliance team at compliance@albertamsa.ca.

SIGNATURE				
Signature	"Original Signed"	Signature Date	May 30, 2017	
Name	Doug Doll	Title	Director, Compliance and Corporate Services	