

April 25, 2005

NOTICE TO PARTICIPANTS

RE: Information Disclosure Procedure (IDP) - Process Change is Delayed

The MSA notice dated April 12 indicated that the improved outage reports would be available as of April 26, 2005. Due to some minor issues we will not be able to launch the reporting tool as previously planned and will require some additional time to ensure the outage graphs are reflecting the submitted information in an appropriate manner.

The MSA wishes to thank participants for their cooperation in this effort and requires the continued dual submission of outage information to continue until further notice.

Participants will continue to submit outage and derate information via emails to outage.scheduling@aeso.ca as well as through the ETS system entering TDE values in the appropriate manner. We will be comparing the submitted emails to the TDE values to evaluate instances of conflicting submissions.

Outage reports will continue to be published on the MSA website three times a day until we are satisfied with the data quality and the automated charting tool performance.

The Trading Practices Guideline (TPG) will continue to be enforced throughout this transition period and disclosure of outage information should continue to be done prior to taking commercial action.

The MSA appreciates your assistance in this endeavor and please accept our apologies for the slight delay in switching over to the enhanced system of providing outage reports to the market.

Yours truly,

“Original Signed”

Mike Nozdryn-Plotnicki
Manager, Market Monitoring