

NOTICE OF SPECIFIED PENALTY

Date of Issue: February 12, 2025		Payment Due Date: March 12, 2025	
MSA File Number	2024-320	Specified Penalty Amount	\$500
Market Participant Name	International Paper Canada Pulp Holdings ULC		
Asset ID (if applicable)	WEY1	Self-Report	<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO
ISO Rule Section	203.3	Date of Contravention	January 5, 2024
Date of Referral/Self Report	September 9, 2024	This is the first contravention by this asset for this section of the ISO rules within a rolling 12-month period.	

MSA FINDINGS

On January 5, 2024, at approximately 00:39, the WEY1 asset experienced an operational deviation which caused the generation level to begin decreasing, reaching 0 MW at 1:05. An available capability (AC) restatement was made at 00:44 to 10 MW for the hours ending 01 and onwards. The asset continued to generate 0 MW; however, a restatement to 0 MW was not made until 03:06 on January 5, 2024.

Section 203.3 of the ISO rules states, in part:

2(1) A pool participant must only submit an available capability restatement revising the available capability of a source asset if such revision is:

- (a) as a result of an acceptable operational reason;
- (b) in relation to an operational deviation and required under subsection 5(3) of section 203.4 of the ISO rules, Delivery Requirements for Energy; or
- (c) in order to reflect the output of the source asset which is restricted during either one (1) or both of commissioning and testing under section 505.3 of the ISO rules, Coordinating Synchronization, Commissioning, WECC Testing and Ancillary Services Testing or under section 505.4 of the ISO rules, Coordinating Operational Testing.

(2) A pool participant that submits an offer must, if there is a change to the available capability of the source asset as a result of any of the circumstances outlined in subsections 2(1)(a), (b) or (c), submit an available capability restatement revising the available capability for the applicable hours, as soon as reasonably practicable.

The MSA is satisfied that the conduct was a contravention of section 203.3 of the ISO rules.

DELIVERY OF PAYMENT

Payment can be made by electronic funds transfer (EFT). Please reach out to compliance@albertamsa.ca for instructions. When submitting the EFT, please send an email to AU.FinOps@gov.ab.ca, compliance@albertamsa.ca and enforcement@auc.ab.ca noting the MSA file #, market participant name, name as appears on bank account, payment amount and the date of the payment. Questions can be directed to compliance@albertamsa.ca.

NOTICE

The Market Surveillance Administrator (MSA) is granted the power and authority under s. 52 of the *Alberta Utilities Commission Act* to issue a Notice of Specified Penalty where the MSA is satisfied that a person has contravened an ISO rule. Specified penalties are set out in AUC Rule 019.

In accordance with the relevant enactments and rules, a dispute regarding the issuance of a Notice of Specified Penalty or failure to pay the specified penalty in accordance with this notice will result in a hearing or other proceeding before the AUC.

In accordance with s. 5.1 of AUC Rule 019 this Notice of Specified Penalty will be made public no earlier than receipt of confirmation of payment from the Commission and no later than 45 days after issuance. The MSA will, if applicable, also post on its website the link to any decision of the AUC respecting the specified penalty.

If your organization disputes the issuance of this Notice of Specified Penalty, or if you have any other questions or comments regarding this matter, please contact the MSA compliance team at compliance@albertamsa.ca.

APPROVED BY

Mark Nesbitt, Director, Enforcement on February 12, 2025