

## NOTICE OF SPECIFIED PENALTY

Date of Issue: September 16, 2014

Payment Due Date: October 16, 2014

MSA File Number:	2014-287	<b>Specified Penalty Amount:</b>	\$750
Market Participant Name:	Powerex Corp.		
Asset ID (if applicable):	FNG1	Self Report	<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO
ISO Rule:	203.3	Date of Contravention:	August 7-8, 2014
Date of Referral/Self Report:	August 22, 2014	This is the second contravention by this asset for this rule within a rolling 12 month period.	

### EVENT DETAILS

On August 7, 2014 at 19:42, the FNG1 generating asset received an advance dispatch instruction to move from the prevailing dispatch level of 55 MW to 42 MW effective at 20:00. In order to ramp unit output to the new dispatch level, FNG1 was required to change its operating mode prompting a reduction in the available capability (AC) of the unit. Following the 19:42 dispatch, however, the declared AC for FNG1 remained unchanged at 59 MW until approximately 11:39 on August 8, 2014. ISO rule 203.3 indicates that a pool participant that submits an offer must, if there is a change to the available capability of the source asset as a result of an acceptable operational reason, submit an available capability restatement revising the available capability for the applicable hours, as soon as reasonably practicable.

### FINDINGS

Based upon the information obtained by the MSA, the MSA is satisfied that the event was a contravention of ISO Rule 203.3.

### MATERIAL FACTS

The material facts relied upon by the MSA include the following:

1. Self-report from Powerex Corp. to the MSA dated August 22, 2014.
2. AESO generation, restatement, and dispatch data for FNG1 for August 7-8, 2014.

### DELIVERY OF PAYMENT

Payment by cheque or certified funds is to be made out to the "General Revenue Fund c/o Minister of Finance", and delivered to the Alberta Utilities Commission (AUC) at: 4th Floor, 425 - 1st Street S.W., Calgary, Alberta, T2P 3L8. Questions in respect of delivery of payment should be addressed to the Director of Finance, AUC. The payment should reference this notice and related MSA File #. Delivery of payment should also be confirmed by email to [compliance@albertamsa.ca](mailto:compliance@albertamsa.ca), with copy to the following AUC personnel: Sabi Ghavami (Director, Finance) [sabi.ghavami@auc.ab.ca](mailto:sabi.ghavami@auc.ab.ca), and Darin Lowther (Director, Market Rules) [darin.lowther@auc.ab.ca](mailto:darin.lowther@auc.ab.ca).

### NOTICE

The Market Surveillance Administrator (MSA) is granted the power and authority under s. 52 of the *Alberta Utilities Commission Act* to issue a Notice of Specified Penalty where the MSA is satisfied that a person has contravened an ISO rule. Specified penalties are set out in AUC Rule 019.

In accordance with the relevant enactments and rules, a dispute regarding the issuance of a Notice of Specified Penalty or failure to pay the specified penalty in accordance with this notice will result in a hearing or other proceeding before the AUC.

In accordance with s. 5(1) of AUC Rule 019 this Notice of Specified Penalty will be made public no earlier than receipt of confirmation of payment from the Commission and no later than 45 days after issuance. The MSA will, if applicable, also post on its website the link to any decision of the AUC respecting the specified penalty.

If your organization disputes the issuance of this Notice of Specified Penalty, or if you have any other questions or comments regarding this matter, please contact the MSA compliance team at [compliance@albertamsa.ca](mailto:compliance@albertamsa.ca).

### SIGNATURE

Signature:	"Original Signed"	Signature Date:	September 16, 2014
Name:	Doug Doll	Title:	Manager Compliance and Corporate Services